

Squire Hill Road & Long Mountain Road

New Milford, Connecticut




Data Collection

- **Survey/Mapping**
- **Wetlands**
- **Utilities**



Due Diligence



- **Subsurface Investigations**
- **Pipe Conditions**
- **Private Properties**

Sample Findings – Squire Hill Road

Runoff Issues



Mature Trees



Deteriorated Pipes




Pavement Conditions

Sample Findings – Long Mountain Road



Protective Railings

Sensitive Natural Resources



Mature Trees



Drainage Conditions



Pavement Conditions

Local Insight

- **Residents/Property Owners**
- **Motorists**
- **Emergency Services**
- **Public Works**
- **Other Stakeholders**

*Your input is critically **IMPORTANT** to us.*